

200220 96478001




FIG 1B

Section AA




FIG 1C

Rotor

164

Section BB'





FIG 1D

SPRINGS

SPRINGS






FIG. 2B




FIG. 3




FIG. 4




FIG. 5




FIG. 6






FIG. 7







FIG. 8a






FIG. 8e




FIG. 8f




FIG. 8g

